


REPLACEMENT SHEET

BEST AVAILABLE COPY


File(F), Edit, View, Parts, Path(P), Expansion function(X), Interference(C)
Window(W), Help(H)



Subassembly composition	Composition
Display	
Edit	
Measuring	
Interference check	
Control check	
Work completed	
Point	
Pending	
Return to just before position	
Property	

Add
Delete
Rename
Parts Exchange

Reference Plane
Work Coordinate
Reference (M)



Edit	Add
Offset	Delete
Displaying Section	
Display Attribute	
Measuring Distance	

FIGURE 16



REPLACEMENT SHEET

BEST AVAILABLE COPY

File(F), Edit, View, Parts, Path(P), Expansion function(X), Interference(C)
Window(W), Help(H)




FIGURE 24